

Product	Hoofdproduct	REQ nr.	Klasse	Certif.inst.	Certificaatnr	Geldig tot	NCP	Datum
Wijzigingen: Vetgedrukt								
5815NT	GS913N		2	BOSEC	B-503-0024	7-10-2009	IMH00201-G	vervallen
AD011	AD011		2	Telefication	C0010232	12-5-2011		
AD044	AD011		2	Telefication	C0010232	12-5-2011		
AD111	AD011		2	Telefication	C0010232	12-5-2011		
AMK4SLSA			3	Vds-C	G191021	3-3-2009	IPA00203-C	vervallen
AS270	AS270		2	BOSEC	B-503-0010/b	10-6-2009	ILF00221-SI	14-07-07
AS271	AS270		2	BOSEC	B-503-0010/b	10-6-2009	ILF00222-SI	14-07-07
AS272	AS270		2	BOSEC	B-503-0010/b	10-6-2009		
AS273	AS270		2	BOSEC	B-503-0010/b	10-6-2009		
AS610(S1)	AS610		2	BOSEC	B-503-0018/a	27-8-2009	IMI00204-SI	28-07-07
AS630(S1)	AS610		2	BOSEC	B-503-0018/a	27-8-2009	IMI00205-SI	28-07-07
ATS1001	ATS2001		2	BOSEC	B-503-0006/b	11-3-2009		
ATS1100	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010	IMI00216-B	03-07-07
ATS1105	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010	INB00205-B	03-07-07
ATS1110	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010		
ATS1111	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010		
ATS1115	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010		
ATS1116	ATS1100		2	BOSEC	B-503-0044/A	7-9-2010		
ATS1190	ATS1192		2	BOSEC	B-503-0005/a	11-3-2009	INB00206-UB	vervallen
ATS1192	ATS1192		2	BOSEC	B-503-0005/a	11-3-2009	IPI00203-UB	16-09-08
ATS1201	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00206-UB	03-07-07
ATS1202	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00207-UB	03-07-07
ATS1210	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00208-UB	03-07-07
ATS1211	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	INCO0213-UB	03-07-07
ATS1220	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00209-UB	03-07-07
ATS1290	EV435-AD		2	Telefication	Incert C0010232	12-5-2011		
ATS1330	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010		
ATS1640	ATS1640		2	BOSEC	B-503-0055	21-4-2011	INCO0214-BH	vervallen
ATS1641	ATS1640		2	BOSEC	B-503-0055	21-4-2011		
ATS1642	ATS1640		2	BOSEC	B-503-0055	21-4-2011	INCO0215-BH	vervallen
ATS1643	ATS1640		2	BOSEC	B-503-0055	21-4-2011	INCO0216-BH	vervallen
ATS1740	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010		
ATS1741	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010		
ATS1743	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010		
ATS1801	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00213-UB	03-07-07
ATS1806		REC024	2	Telefication	06223502/AA/00	7-12-2009		
ATS1810	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00210-UB	03-07-07
ATS1811	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00211-UB	03-07-07
ATS1820	ATS7200		2	BOSEC	B-0503-0033/b	6-6-2010	IMI00212-UB	03-07-07
ATS2001			2	BOSEC	B-503-0006/b	11-3-2009	INCO0217-CCS	03-07-08
ATS3001	ATS2001		2	BOSEC	B-503-0006/b	11-3-2009	INCO0218-CCS	03-07-08
ATS4001	ATS2001		2	BOSEC	B-503-0006/b	11-3-2009	IMI00219-CCS	vervallen
ATS7100	ATS7110		2	BOSEC	B503-0027/c	12-1-2010	INCO0201-K	vervallen
ATS7110	ATS7110		2	BOSEC	B503-0027/c	12-1-2010	IPF00201-K	18-06-08
ATS7120	ATS7110		2	BOSEC	B503-0027/c	12-1-2010		
ATS7121	ATS7110		2	BOSEC	B503-0027/c	12-1-2010		
ATS7300	ATS7110		2	BOSEC	B503-0027/c	12-1-2010		
BS121N			2	VDS	G101077	18-5-2011	ILF00217-V	vervallen
BS122N			2	VDS	G101078	24-2-2008	ILF00218-V	vervallen
BS127N			2	VDS	G101120	18-5-2011	ILF00211-V	vervallen
BS129N			2	VDS	G101079	30-11-2007	INCO0219-V	vervallen
BS130N			2	VDS	G101080	18-5-2011	ILF00210-V	vervallen
BS131N			2	VDS	G101081	30-11-2007	ILI00202-V	vervallen
BS132N			2	VDS	G102010	27-7-2009	ILF00212-V	vervallen
CB05A	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00202-A	vervallen
CB05B	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00202-A	vervallen
CB10A	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00203-A	vervallen
CB10B	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00203-A	vervallen
CB15A	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00204-A	vervallen

Product	Hoofdproduct	REQ nr.	Klasse	Certif.inst.	Certificaatnr	Geldig tot	NCP	Datum
Wijzigingen: Vetgedrukt								
CB15B	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00204-A	vervallen
CB20A	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00205-A	vervallen
CB20B	CB05A		2	BOSEC	B-503-0002	11-3-2009	INK00205-A	vervallen
CD15001	CD9501		2	BOSEC	B-503-0021/a	10-9-2009	IJB00205-CCS	vervallen
CD3004	CD3004		2	BOSEC	B-503-0058	5-6-2011	ILF00216-UB	vervallen
CD3008	CD3008		2	BOSEC	B-503-0019	10-9-2009	IJL00201-B	vervallen
CD3008-PROX	CD3008		2	BOSEC	B-503-0019	10-9-2009	IMD00223-B	vervallen
CD3009	CD3008		2	BOSEC	B-503-0019	10-9-2009	IJL00202-B	vervallen
CD3048	CD3008		2	BOSEC	B-503-0019	10-9-2009	IJL00205-B	vervallen
CD3049	CD3008		2	BOSEC	B-503-0019	10-9-2009	IJL00206-B	vervallen
CD3401SBSCB	CD9501		2	BOSEC	B-503-0021/a	10-9-2009	IJB00209-CCS	vervallen
CD3401SCB	CD9501		2	BOSEC	B-503-0021/a	10-9-2009	IJB00208-CCS	vervallen
CD7201	CD9501		2	BOSEC	B-503-0021/a	10-9-2009	IJB00203-CCS	vervallen
CD9005	CD9031		2	BOSEC	B-503-0023	7-10-2009	ILF00215-UB	vervallen
CD9031	CD9031		2	BOSEC	B-503-0023	7-10-2009	ILF00201-UB	vervallen
CD9501	CD9501		2	BOSEC	B-503-0021/a	10-9-2009	IJB00201-CCS	vervallen
CP4003	CD3004		2	BOSEC	B-503-0058	5-6-2011	IMD00202-UB	vervallen
CS1700			2	BOSEC	B-503-0049	24-9-2010	IPK00201-UB	15-12-07
CS175M			2	BOSEC	Incert C0010002	8-10-2007	INK00206-CCS	vervallen
CS216	CS216		2	BOSEC	B-503-0051	25-10-2010	INCO0211-UB	vervallen
CS275(S1)	CS375		2	BOSEC	B-503-0007/c	11-3-2009	INB00204-CCS	03-07-07
CS375	CS375		2	BOSEC	B-503-0007/c	11-3-2009	IPF00202-CCS	18-06-07
CS5018	CS5500		2	BOSEC	B-503-0008/b	22-4-2009	IMI00215-B	vervallen
CS507	CS216		2	BOSEC	B-503-0051	25-10-2010	INCO0212-UB	vervallen
CS535			2	BOSEC	Incert C0010001	8-10-2007	INK00207-UB	vervallen
CS5500			2	BOSEC	B-503-0008/b	22-4-2009	IPI00202-B	vervallen
CS575(S1)	CS375		2	BOSEC	B-503-0007/c	11-3-2009	IMI00218-CCS	03-07-07
CS575M	CS375		2	BOSEC	B-503-0007/c	11-3-2009		
CS7050			2	BOSEC	B-503-0047	24-9-2010	IPK00202-UB	15-12-07
CS7501			2	BOSEC	B-503-0028	7-3-2010	IPB00202-K	vervallen
CS875M	CS375		2	BOSEC	B-503-0007/c	11-3-2009	IPF00203-CCS	18-06-07
DC101	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00210-C	vervallen
DC102	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IFJ00201-C	vervallen
DC102R4.7	DC101		2	BOSEC	B-503-0016/b	27-8-2009	INCO0220-C	vervallen
DC103	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00211-C	vervallen
DC104	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IFJ00202-C	vervallen
DC106	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00213-C	vervallen
DC106R4.7	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00206-C	vervallen
DC107	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00214-C	vervallen
DC107R4.7	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00207-C	vervallen
DC108	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00215-C	vervallen
DC108R4.7	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00208-C	vervallen
DC109	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IFJ00206-C	vervallen
DC110	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00205-C	vervallen
DC113	DC113		2	BOSEC	B-503-0017	27-8-2009	IAI00217-C	vervallen
DC114	DC113		2	BOSEC	B-503-0017	27-8-2009	IMD00209-C	vervallen
DC115	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00217-C	vervallen
DC116	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IFJ00204-C	vervallen
DC118	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IAI00218-C	vervallen
DC120	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00210-C	vervallen
DC121	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00216-C	vervallen
DC123	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00213-C	vervallen
DC124	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00214-C	vervallen
DC126	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00215-C	vervallen
DC127	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00211-C	vervallen
DC129	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00217-C	vervallen
DC130	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00218-C	vervallen
DC134	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00210-C	vervallen
DC135	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00204-C	vervallen

Product	Hoofdproduct	REQ nr.	Klasse	Certif.inst.	Certificaatnr	Geldig tot	NCP	Datum
Wijzigingen: Vetgedrukt								
DC137	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00211-C	vervallen
DC140	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IFJ00205-C	vervallen
DC141	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00212-C	vervallen
DC142	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IJB00209-C	vervallen
DC143	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00203-C	vervallen
DC501	DC101		2	BOSEC	B-503-0016/b	27-8-2009	IMD00212-C	vervallen
DD100	DD100		2	BOSEC	B-503-0013	27-8-2009	ILIO0201-D	vervallen
DD100PI	DD100		2	BOSEC	B-503-0013	27-8-2009	ILIO0203-D	vervallen
DD105	DD100		2	BOSEC	B-503-0013	27-8-2009	ILIO0204-D	vervallen
DD205RFW8			2	CEBEC	C0010320	17-8-2012		
DD325-P	DD325-P		2	BOSEC	B-503-0041	23-8-2010	IGF00201-D	31-12-07
DD326-P	DD325-P		2	BOSEC	B-503-0041	23-8-2010	IGF00202-D	31-12-07
DD455	DD455		2	BOSEC	B-503-0043	23-8-2010	IKC00201-D	08-09-07
DD455S	DD455		2	BOSEC	B-503-0043	23-8-2010	IKC00205-D	08-09-07
DD475	DD455		2	BOSEC	B-503-0043	23-8-2010	IKC00203-D	08-09-07
DD475S	DD455		2	BOSEC	B-503-0043	23-8-2010	IKC00206-D	08-09-07
DD495	DD455		2	BOSEC	B-503-0043	23-8-2010	IMD00213-D	vervallen
EV100	EV100		2	BOSEC	B-503-0059	25-7-2011	INB00202-P	vervallen
EV100-CS	EV100-MSIR	REC0030	2	Telefication	06223504/AA/00	21-2-2010		
EV100-MS	EV100-MSIR	REC0030	2	Telefication	06223504/AA/00	21-2-2010		
EV100-MSIR	EV100-MSIR	REC0030	2	Telefication	06223504/AA/00	21-2-2010		
EV100PI	EV100		2	BOSEC	B-503-0059	25-7-2011	INB00201-P	vervallen
EV105	EV100		2	BOSEC	B-503-0059	25-7-2011	INB00203-P	vervallen
EV125-P	EV125-P		2	BOSEC	B-503-0011	27-8-2009	III00202-P	vervallen
EV125P-D	EV125P-D		2	VDS	G196513	31-5-2010	IMF00201-P	vervallen
EV126P-D	EV125P-D		2	VDS	G196513	31-5-2010	III00203-P	vervallen
EV425-P	EV125-P		2	BOSEC	B-503-0011	27-8-2009	III00206-P	vervallen
EV425P-D	EV425P-D		2	VDS	G196520	31-5-2010	IMF00202-P	vervallen
EV426P-D	EV425P-D		2	VDS	G196520	31-5-2010		
EV435-AD	EV435-AD		2	Telefication	Incert C0010232	12-5-2011		
EV435AM	EV435AM	REC0031	3	VDS-c	G197016	28-2-2011	III00210-P	vervallen
EV436AM	EV435AM	REC0031	3	VDS-c	G197016	28-2-2011	III00211-P	vervallen
EV435AM-AD	EV435-AD		2	Telefication	Incert C0010232	12-5-2011		
EV455AM	EV455AM		3	VDS-c	G197046	28-2-2011	III00212-P	vervallen
EV456AM	EV455AM		3	VDS-c	G197046	28-2-2011	III00213-P	vervallen
EV455-P	EV125-P		2	BOSEC	B-503-0011	27-8-2009	III00214-P	vervallen
EV475AM	EV475AM		3	VDS-c	G101004	29-1-2011	IMH00207-P	vervallen
EV476AM	EV475AM		3	VDS-c	G101004	29-1-2011		
EV646			2	VDS	G196524	31-12-2007	IDK00208-P	vervallen
EV666-D	EV669-D		2	BOSEC	B-503-0031	25-3-2010	ILF00220-P	10-07-07
EV669-D	EV669-D		2	BOSEC	B-503-0031	25-3-2010	ILF00219-P	10-07-07
GS620BN	GS620N		2	BOSEC	B-503-0026	12-1-2010	IFJ00212-T	vervallen
GS620N	GS620N		2	BOSEC	B-503-0026	12-1-2010	ILF00202-T	vervallen
GS620P5BN	GS620N		2	BOSEC	B-503-0026	12-1-2010	ILF00203-T	vervallen
GS620P5N	GS620N		2	BOSEC	B-503-0026	12-1-2010	IFJ00209-G	vervallen
GS711	GS620N		2	BOSEC	B-503-0026	12-1-2010	IFJ00210-G	vervallen
GS711B	GS620N		2	BOSEC	B-503-0026	12-1-2010	IFJ00211-G	vervallen
GS913N	GS913N		2	BOSEC	B-503-0024	7-10-2009	IMD00215-G	vervallen
MB800	RC900		2	BOSEC	B-503-0056	11-5-2011	ILF00209-UB	vervallen
MK48SLSA	MK48SLSA		3	Vds-C	G191019	3-3-2009	IPA00202-C	vervallen
MK48SLSA4	MK48SLSA		3	Vds-C	G191019	3-3-2009	IPA00202-C	vervallen
MM110	MM110		2	BOSEC	B-503-0015	27-8-2009	IGB00204-C	vervallen
MM115	MM110		2	BOSEC	B-503-0015	27-8-2009	IGB00205-C	vervallen
OH-NetRec-Software		REC025	0	Telefication	06223501/AA/00	7-11-2009		
OH-NetRec-100	OH-NetRec-Software	REC025	0	Telefication	06223501/AA/00	7-11-2009		
OH-NetRec-1000	OH-NetRec-Software	REC025	0	Telefication	06223501/AA/00	7-11-2009		

Product	Hoofdproduct	REQ nr.	Klasse	Certif.inst.	Certificaatnr	Geldig tot	NCP	Datum
Wijzigingen: Vetgedrukt								
OH-NetRec-SDK	OH-NetRec- Software	REC025	0	Telefication	06223501/AA/00	7-11-2009		
PG822	PG822		2	BOSEC	B-503-0025	16-10-2009	ILF00205-V	vervallen
PG824	PG822		2	BOSEC	B-503-0025	16-10-2009	ILF00206-V	vervallen
PG829	PG822		2	BOSEC	B-503-0025	16-10-2009	IMD00216-V	vervallen
RC213	RC900		2	BOSEC	B-503-0056	11-5-2011	ILI002013-P	vervallen
RC813	RC900		2	BOSEC	B-503-0056	11-5-2011	IMD00217-UB	vervallen
RC814	RC900		2	BOSEC	B-503-0056	11-5-2011	ILI002014-UB	vervallen
RC900	RC900		2	BOSEC	B-503-0056	11-5-2011		
RD5060	RD6201		2	BOSEC	B-503-0020	10-9-2009	IMD00201-UB	vervallen
RD6201	RD6201		2	BOSEC	B-503-0020	10-9-2009	ILI002015-K	vervallen
RD6201-ISDN	RD6201		2	BOSEC	B-503-0020	10-9-2009	IMD00222-K	vervallen
RF300W8			2	BOSEC	B-503-0039/a	23-8-2010	IMI00217-C	03-07-07
RF354W8			2	BOSEC	B-503-0053	23-3-2011		
RF425W8	RF425W8		2	BOSEC	B-503-0009/b	23-4-2009	IMI00203-P	03-07-07
RF425W8PI	RF425W8		2	BOSEC	B-503-0009/b	23-4-2009	IOI00201-P	vervallen
RX16W8CA-pcb	RX8W8CA-pcb		2	BOSEC	B-503-0045/a	24-9-2010	IMI00202-UB	03-07-07
RX8W8CA-pcb	RX8W8CA-pcb		2	BOSEC	B-503-0045/a	24-9-2010	IMI00201-UB	03-07-07
RXW8OM	RX8W8CA-pcb		2	BOSEC	B-503-0045/a	24-9-2010		
RXWEH00	RX8W8CA-pcb		2	BOSEC	B-503-0045/a	24-9-2010	INC00210-BH	03-07-07
VE735	VE735		2	VDS	G104516	30-9-2010	IPF00204-P	18-06-07
VE735AM	VE735AM	REC0007	3	Telefication	05229005/AA/02	2-8-2009	IQH00201-P	31-08-08
VE736	VE735		2	VDS	G104516	30-9-2010	IPF00205-P	18-06-07
VE736AM	VE735AM	REC0007	3	Telefication	05229005/AA/02	2-8-2009	IQH00202-P	31-08-08
VV602-PLUS	VV602-PLUS		3	Vds-C	G101142	22-10-2007	INC00205-D	22-10-07
VV622-PLUS	VV622-PLUS		3	Vds-C	G101142	22-10-2007	INC00208-D	22-10-07
VV700	VV700		3	Vds-C	G103021	18-3-2009	IOE00201-T	vervallen
VVS700	VV700		3	Vds-C	G103021	18-3-2009	IOE00202-T	vervallen